Ardissone Building Committee Report February 16, 2023

The following contains the final report from the Building Committee to the Ardissone Board on using the opportunities presented in required maintenance projects to update the island campus. You can access the full powerpoint on the Ardissone website.

Committee Members

Brian Walker Unit 506 briancwalker@me.com 616-836-9722

Jim Walsh Unit 504 jiwalsh2018@gmail.com 704-507-0551

Kathy Reno Unit 105 karenreno@sbcglobal.net 847-400-4816

Doug Johnson Unit 204 <u>c.douglas.johnson@gmail.com</u> 309-738-9408

Varney Hintlian Unit 104 vhintlian@yahoo.com 239-902-4872



PRESENTATION

Naples, Florida 34103

The Ardissone

Content

- Current Situation
- Design Vision
- Budget
- Return on Investment
- Summary
- Next Steps
- Frequently Asked Questions

Current Situation

- Building Committee Objectives
 - Understand Required Maintenance From Structural Engineer
 - Determine Residents Desired Changes
 - Develop a Design Vision for Ardissone based on owner feedback
 - Develop a Budget and Schedule to Achieve the Vision
- Required Maintenance
 - *Roof Caps
 - *Paint
 - *Railings
 - *Planter Boxes
 - *Landscaping
- New Florida Reserve Laws
 - Implementation 12/31/24
 - Reserves Fully Funded

Phased Maintenance Repairs & Improvements Asterisks * denote maintenance items required by FL Laws

- Phase 1- 2023 to 2024
 - *Replace Roof Cap
 - *Paint all building Exteriors
 - *Replace all Railings
 - *Water Proof or Remove Planters
 - Repair Landscaping Around Buildings
 - Replace Parking Garage In-fills
- Phase 2 2025 to 2026
 - New Elevator Cab Finishes
 - New Landscape and Fountains at Entry
 - Replace Pavers in Drive and Pool
 - Replace Pool Furnishings
- Future Possibilities
 - Aesthetic Improvements to Building Façade
 - New Amenities

Member Feedback

RESIDENT DISLIKES

General Comments
 Old / Plain, Dock Area (Hoses, Electrical), Air Conditioning, Pedestrian Gate, Gutters, No secure package delivery area

	delivery dred		
•	Building Appearance		
	• Color	27 Units	(82%)
	Dated Style	21 Units	(63%)
	Shutter Look	6 Units	(18%)
	Railings (Outdated)	6 Units	(18%)
	Rough Stucco	14 Units	(42%)
	Tile floors	5 Units	(15%)
			(15/0)
	 No uniformity from water (i.e. colors, windows, etc. MASTER PLAN) 	5 Units	(15%)
	• De-med the look	16 Units	(48%)
•	Roof		(0.4~)
	Contemporary Roof	12 Units	(36%)
	Insurance Premium / Roof	5 Units	(15%)
•	Pool		
	 Appearance of pool area / pool pavers 	12 Units	(36%)
	Pool bathroom	12 Units	(36%)
•	Safety & Security		(/
	Gate Entry	12 Units	(36%)
	Signage	10 Units	(30%)
	Security	5 Units	(15%)
•		5 011113	(13/6)
•	Parking & Traffic	1.4.110:40	(4007)
	Guest parking	14 Units	(42%)
	Traffic Concerns	10 Units	(30%)
•	Landscaping (Ugly & Smells)	15 Units	(45%)

Member Feedback

WHAT IS THE ARDISSONE MISSING?

•	Appearance		
	Lighter colors, Fresh look Modern look	20 Units	(60%)
•	Pool Area Pool Bar Fire tables Privacy at pool Water wall in front of pool	10 Units 10 Units 10 Units 10 Units	(30%) (30%) (30%) (30%)
•	Social Room	16 Units	(48%)
•	Workout room	13 Units	(39%)
•	Water Features Fountains / Water Walls Signage w/water feature Boating Area Covers for boat docks	5 Units 5 Units	(15%) (15%)
	 Canoe/paddle board launch 	5 Units	(15%)
•	Parking & Storage Areas Secure Bike storage Guest parking (big problem) Better car parking, Community storage areas	15 Units 5 Units 5 Units	<mark>(45</mark> %) (15%) (15%)
•	Security Areas	5 H - 11	(1.507)
_	Gate House, One entry access system, Better pedestrian gate Lights & Environmental	5 Units	(15%)
•	Lights & Environmental Generators Solar Panels	6 Units 2 Units	(18%) (6%)
•	Roof New roof	16 Units	48%)
•	Flat metal Miscellaneous		40/0]
	Any improvement would be great	20 Units	(60%)

Current Exterior





Existing Exterior







Existing Exterior







Existing Exterior







Existing Exterior







Existing Exterior



Design Vision



Phase 1 Design Required Maintenance with upgrades



Phase 1 Design Required Maintenance with upgrades





Phase 1 Design Required Maintenance with upgrades

Phase 1 Budget

Item	Total	Per Unit
*Replace Roof	\$775,000	\$24,000
*Paint Buildings	\$540,000	\$16,000
*Replace Railings	\$325,000	\$10,000
*Water-Proof/Remove Planters	\$171,000	\$5,000
*Repair Landscaping	\$85,000	\$3,000
*Contingency	\$100,000	\$3,000
Sub Total	\$1,996,000	\$61,000
Standing Seam Roof	\$74,000	\$2,000
Replace In-Fills	\$250,000	\$8,000
Smooth Coat Stucco	\$150,000	\$5,000
Remove Arches	\$100,000	\$3,000
Contingency	\$30,000	\$1,000
New Design Increment	\$604,000	\$19,000
Total Phase 1	\$2,600,000	\$80,000

Phase 2





Phase 2 Exterior with water feature, New pavers, pool finishes & Landscaping



Phase 2 Exterior with water feature, New pavers, pool finishes & Landscaping



Phase 2

Concept Elevator Look

Interior of Elevator Cabs to match



Phase 2 Budget

Item	Total	Per Unit
New Elevator Cabs	\$125,000	\$4,000
Landscape and Fountains at Entry	\$50,000	\$1,000
Drive & Pool Pavers	\$350,000	\$11,000
Pool Furnishings	\$40,000	\$1,000
Contingency	\$60,000	\$2,000
Total Phase 2	\$625,000	\$19,000

Budget Summary

ITEM	TOTAL	PER UNIT
Phase 1	\$2,600,000	\$80,000
Phase 2	\$625,000	\$19,000
New Signage	\$65,000	\$2,000
Architectur al Fees	\$50,000	\$2,000
Grand Total	\$3,340,000	\$93,000

Return on Investment



Comparative Market Analysis

4400 Gulf Shore BLVD N #6-604 Naples, 34103

Thursday, January 5, 2023

CMA Price Adjustments

This page outlines the subject property versus comparables properties.







Subject Property		
4400 Gulf Shore BLVD N #6-604		
MLS#	222080556	
Status		
List Price	\$3,600,000	
Sold Price	\$3,600,000	
Sold Date	11/8/2022	
Price/SqFt	\$1,387.28	
City	Naples	
Zip	34103	
Sub Condo	ARDISSONE	
Development	PARK SHORE	

Adjust 1820 Gulf Shore BLVD N #402/403 221045884 Active \$9,777,000

Details Adjust 1820 Gulf Shore BLVD N #302 & 303 221045882 Pending \$8,700,000

Cmnty Type Boating, Gated DOM/CDOM 2/1 Baths Beds Bldg Design Low Rise (1-3) Bldg Desc End-Unit, Penthouse Bay, City View Furnished Furnished Rear Expose NE Garage Spc Carport Spc Acres Gulf Access Shutters - Electric Storm Prot Unit Floor Construction 1987

\$1,657.12 Naples 34102 LA PERLE MOORINGS Non-Gated 344/773 4/1 OVD. Mid Rise (4-7) Florida Bay, Partial Gulf Unfurnished NE 3 0.000 Yes/Bridge(s)/Water Indirec Yes/Bridge(s)/Water Indirect Impact Resistant Doors, Imp Concrete Block, Piling, Pou Concrete Block, Poured Co 2022 5,900 No Interior FeaturCable Prewire, Coffered Ce Bar, Built-In Cabinets, Cable 2 Assigned, Guest, Paved F

\$1,474.58 Naples 34102 0 LA PERLE 0 MOORINGS 0 Non-Gated 0 200/773 0 0 0 Mid Rise (4-7) Florida 0 Bay, Partial Gulf 0 Unfurnished 0 NE 0 0 0 0 0 0 0 Yes/Bridge(s)/Water Indirect 0 Impact Resistant Doors, Imp 0 0 Concrete Block, Poured Co 0 0 O 2022 5,900 0 0 0 Bar, Built-In Cabinets, Cabl 0 0 2 Assigned, Guest, Paved F

Parking Covered, Deeded Remarks: Exclusivity and luxury go hand in hand in this

elegant residence positioned on Venetian Bay and highlighting sweeping views of the waterways. Fully remodeled with every detail

Year Built

Appx Liv Ar 2595

Private Spa YNNo

Welcome to La Perie! A rare commodity in a treasured & special location fronting Hurricane Harbor & capturing sensational views of the Guif. With only 13 units, La Perle

Welcome to La Perie! A rare commodity in a treasured & special location fronting Hurricane Harbor & capturing sensational views of the Guif. With only 13 units, La Perle

Price Total Adjustments Adjusted Price

\$9,777,000 \$0 \$9,777,000

\$8,700,000 \$0 \$8,700,000



Thursday, January 5, 2023

Pricing Recommendation

This page suggests a recommended listing price based on a thorough analysis of your property.

The Subject Property in my opinion could increase in sq ft price in my opinion between \$200-300sq ft

The subject property has many superior qualities in both location and build. The comparable in LA PERLE lacks the location that this property offers. The style that is selected in the rendering is very stylish and I would say part of a timeless selection meaning that it will stay up to date for a larger period of time.

Four Season beach Club...

I wanted to point out that the new project on the beach. It is located where the Naples Beach Club was formally located. These units have pre-sold at 4k per sq ft. Down near the beach is becoming one of the most desirable places to live which pushes up per sq ft prices especially being refreshed on the exterior.

Researched and prepared by **Michael Condello**MVP Realty Associates LLC



Summary

- We have maintenance that must be completed.
- Florida law will require funding even if we don't complete.
- A modest increment will drive a return from our maintenance.
- The design vision is based on your feedback.
- We have phased and scoped the project to be affordable.

Next Steps

- Approve the design direction.
- Approve the scope of phase 1.
- Develop detailed construction documents.
- Obtain construction bids.
- Refine the schedule of construction.

Frequently Asked Questions

Frequently Asked Questions

Q. Why are we talking about any projects at the Ardissone?

A. As presented over the past year in many of the updates from the board, the issues of our tile roof, water intrusion into our cement floor/ceilings and walls from the remaining planters and railing nonconformance to code (this becomes an issue with any modifications of current railings) all need to be addressed over the next few years due to them being past their useful life.

Many residents expressed a desire to look at the potential of updating the look of the Ardissone while doing these required upgrades. A Building Committee was created and after additional review with engineers of the roof, planters, and railings, it was presented to Ardissone residents who then voted to spend funds to bring in an architectural firm to create an overall master plan for our island campus. Don Stevenson, CEO/Architect of Lotus Architecture was contracted to prepare a Master Plan for our association.

The Master Plan was presented to Ardissonne residents in attendance on January 6, 2023 by the Building Committee members, chaired by Brian Walker and Jim Walsh. It showed three phases that could be completed over a number of years. Each phase is a separate and distinct vote by Ardissone residents.

Q. If the flat roofs are our real roofing, why do we need to deal with the façade roof that is the barrel tile?

A. The tile roofs are not just a façade but actual sloped roofs. About 18 months ago there was a leak into a condo from this roof. Crowther Roofing (good one) was brought in to inspect that roof and others. They found that there had been water intrusion into the plywood of the tiled roof in multiple places. The main factor on a tiled roof is an intact underlayment which is not intact nor serving its role in protecting from water. The Ardissone underlayment was installed in 1997 and is past its useful life. This impacts an insurance company's assessment of risk which makes securing acceptable insurance difficult.

Q. I heard there are three phases included in the proposal. Are we voting on each of the phases all at once?

A. No, at this time the item that will be coming to the residents for vote is for an assessment above the basic replacement cost for the roof, railings and planters. The total incremental assessment beyond the basic is estimated to be \$19,000 per unit for total phase one assessment of \$80,000. The Building Committee is recommending that the monies allocated for these replacements be spent so that an upgraded look to our buildings can be achieved with a much lower cost overall. The Building Committee has been advised by a highly regarded realtor that this investment should increase the value of our units well above the \$19,000 incremental cost per unit. Phases 2 will be approved at a later time. At this time, a phase 3 is not planned. However, we have developed concepts for "future possibilities" based on the feedback received in our resident focus meetings. These concepts Items may never be brought for a vote due to changes in resident interest.

Frequently Asked Questions

- Q. Why do we need new railings?
- **A.** Matt Maltezos of TRC Engineering assessed railings in each of our buildings and found the following:
 - Railings date back to original building construction late 80's, early 90's
 - Anchor Bolts and railing bases are corroded
 - Condition similar across all six buildings with few exceptions where replacements/upgrades already made
 - Railings no longer meet local and national building codes
 - Recommendation Replace railings with an acceptable standard to be determined by the architect
- Q. I heard there were glass railings on the plan, is that correct?
- **A.** No, Building Committee members early in the process identified the difficulty in keeping glass railings clean in a saltwater environment. At this time, what is being recommended is a stainless steel cable system that visually fades away but is easier for maintenance.
- **Q.** What is the material shown on the renderings that replaces the star cement blocks.
- **A.** The architect has recommended using Knotwood to provide some visual interest. To see Knotwood in use, look at the new electrical box covers. The brown metal railings are Knotwood. This wood be merely used as an architectural design feature. Please note on the renderings provided where it could (note 'could') be applied.
- **Q.** Has anyone checked into the potential of financing this work, either as an association or for individuals.
- **A.** Yes, some exploratory work has been made into financing. At this time with the rise in interest rates, it was determined that would not be in the best interest of the association members. Individual loans are something that could be considered by residents but are not within the purview of the committee.

Future Possibilities



Aesthetic Additions to Façade





Aesthetic Additions to Facade



Aesthectic Additions to Facade



Social Room Concept



Social Room Concept



Gym Concept





Mail & Package Room

